Product Safety Recall



YAMAHA XVS950CUD Motorcycle Engine Oil Leak

MODEL	MODEL	FRAME NUMBER			Affected Units
	YEAR	PREFIX No.	FROM	то	
XVS950CUD	2021	VN077	000121	000185	27

WHAT IS THE DEFECT?

Due to manufacturing issue with the engine crankcase, oil may leak onto the road and come in contact with the rear tyre. This could result in a loss of control of the vehicle.

WHAT IS THE REMEDY?

Yamaha Motor Australia has initiated a Factory Modification Campaign and all affected units must be inspected for an oil leak at the bottom of the engine, if present the engine will be swapped.

WHAT ARE THE HAZARDS?

A loss of vehicle control increases the risk of an accident, which may cause injury or death to rider and/or passenger or other road users.

WHAT TO DO?

Owners of affected motorcycles can contact their local Yamaha Dealer to make an appointment to have their model inspected and fixed free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

http://www.yamaha-motor.com.au/ or CALL 1300 593 600.

If you no longer own the unit, please advise Yamaha Motor Australia on 1300 593 600.

Australian Importer/Distributor Yamaha Motor Australia 489-493 Victoria Street, Wetherill Park NSW, Australia

See <u>www.productsafety.gov.au</u> for other Australian consumer product recalls