

Product Safety Recall



YAMAHA AG125 Motorcycle Fuel Cock

MODEL	MODEL CODE	PREFIX No.	FRAME NUMBER	
			Start	End
AG125	BF85	CE28W	0013630	0014567

WHAT ARE THE DEFECTS?

An incorrect press fitting procedure during assembly may have damaged the fuel cock tube, which may lead to fuel leakage.

WHAT ARE THE HAZARDS?

If fuel leaks in the presence of an ignition source this may cause a fire, increasing the risk of serious injury or death to riders.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the fuel cock assembly replaced.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls