

Product Safety Recall



YAMAHA WR250F (2018-2019), WR450F (2016-2020) Noise Label Replacement

| MODEL | MODEL YEAR | FRAME NUMBER | | |
|--------|------------|--------------|--------|--------|
| | | PREFIX NO. | FROM | TO |
| WR450F | 2016-2018 | CJ19W | 000019 | 007530 |
| WR450F | 2019-2020 | CJ25W | 000311 | 003062 |
| WR250F | 2018-2019 | CG36W | 005415 | 007474 |

WHAT IS THE DEFECT?

Incorrect decibel reading on the noise label.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected WR250F/WR450F models must have the noise label replaced without charge.

WHAT TO DO?

New labels will be available from July, you should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 593 600.

If you no longer own the unit, please advise Yamaha Motor Australia via email cr@yamaha-motor.com.au

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
other Australian consumer product recalls