

# Product Safety Recall



## YAMAHA MY20/21 Tricity (MWD300) Stand Assist System

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX No.	FROM	TO
MWD300	BX95, BX97	2020-2021	SH162	1001	1130

Sold by authorised Yamaha dealers between 1 August 2020 to 31 May 2021

### Defect

In some situations, the standing assist system may not release immediately after deactivation. It has been identified that the current modification has not fully eliminated the release issue with the stand assist system.

### Hazard

If the stand assist does not release immediately, it may prevent the rider from steering, causing loss of control resulting in the rider or passenger being injured.

### What to do

As an interim measure Yamaha requests, you attend your nominated Yamaha dealer to have your stand assist function manually deactivated free of charge. Notification will be supplied when an appropriate solution is available.

### Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

**Australian Importer/Distributor**

**Yamaha Motor Australia**

489-493 Victoria Street, Wetherill Park  
NSW, Australia

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for  
Australian product recall information