

Product Safety Recall



YAMAHA Wolverine RMAX YXE1000 and YXF1000 Side by Side Vehicles MY2021

YEAR	MODEL	MODEL CODE	FRAME NUMBER			PRODUCTION DATE	
			PREFIX NO.	SERIAL FROM	SERIAL TO	FROM	TO
2021	YXF1000EWS	B4J2	AN39W	300261	300480	Feb-21	Jun-21
	YXE1000EWS	B4M3	AN43W	500191	500289	Mar-21	Jun-21

Sold by authorised Yamaha Dealers between 1 March 2021 and 30 June 2021

DEFECT

The fuel tank may have been damaged during the vehicle's assembly.

HAZARD

Fuel may leak from a damaged fuel tank. If fuel leaks in the presence of an ignition source this may cause a fire, increasing the risk of serious injury or death to vehicle occupants.

WHAT TO DO?

Consumers should contact their local Yamaha dealer to arrange for an inspection and replacement fuel tank, where required.

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

CONTACT DETAILS

Contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information