

Product Safety Recall



YAMAHA YZ125SPN/YZ125N Motorcycles MY2022

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX No.	FROM	TO
YZ125	B4X4, B4X8	2022	CE34C	000421	004101

Sold by authorised Yamaha dealers between 1 July 2021 and 15 January 2022

Defect

The shift selector detent spring may dislodge while riding, causing the gear to shift unexpectedly or inhibit gear selection.

Hazard

If the gear shifts unexpectedly or cannot shift properly, there is an increased risk of an accident resulting in injury or death to the rider or bystanders.

What to do

Parts for repair will become available from the end of February 2022. In the meantime, consumers should contact their local Yamaha dealer to arrange for an inspection and temporary modification of the motorcycle, free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information