

Product Safety Recall



YAMAHA OUTBOARD IGNITION CONTROL SOFTWARE UPDATE

Primary ID			
6AL1007281	6AL1007291	6AL1007315	6AL1007332
6KY1000585	6KY1000795	6KY1000939	6KY1001217
6KW1001602	6LF1002050	6LF1003164	

Sold by authorised Yamaha dealers between 1 November 2021 to 30 June 2022

Defect

The ignition coils may be energised when the main key switch is turned ON, this is due to improper Engine Control Unit programming.

Hazard

This spark could ignite unburned fuel in the combustion chamber and could damage the Intake Manifold.

What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this recall carried out free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information