

Product Safety Recall



YAMAHA MY21 Tricity (MWS150) Compliance Plate Exchange

MODEL	MODEL CODE	MODEL YEAR	FRAME NUMBER		
			PREFIX No.	FROM	TO
MWS150	BB8X	2021	SG384	70422	70451

Sold by authorised Yamaha dealers February 2021

Defect

The VIN on the compliance plate was incorrectly stamped and does not match the VIN stamped on the frame.

What to do

Owners of affected vehicles can contact their authorised Yamaha Dealer to schedule an appointment to have the incorrect compliance plate removed and a correctly stamped plate fitted.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information