Product Safety Recall





YAMAHA MT03 Motorcycle Non-Compliant Rear Reflector

| MODEL | MODEL YEAR | FRAME NUMBER | | |
|-------|---------------|--------------|--------|--------|
| | | PREFIX | FROM | то |
| MT03 | 2016-2017 | RH07L | 001001 | 005800 |
| | 2018-2019 | RH127 | 001001 | 002640 |
| | 2020 | RH12R | 001001 | 001440 |

WHAT IS THE DEFECT?

The "REAR REFLECTOR ASSY" on the listed model, may not comply with UN-ECE standard specification for reflection luminosity.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective "REAR REFLECTOR ASSY" replaced with the countermeasure one.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at

http://www.yamaha-motor.com.au/ or CALL 1300 593 600.

If you no longer own the unit, please advise Yamaha Motor Australia on 1300 593 600.

Australian Importer/Distributor Yamaha Motor Australia 489-493 Victoria Street, Wetherill Park NSW, Australia

See <u>www.productsafety.gov.au</u> for other Australian consumer product recalls