

Product Safety Recall



YAMAHA MY22 XTZ690 Tenere Caliper Bolt

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
XTZ690	2022	DM131	001024	001049

Sold by authorised Yamaha dealers between 12 October 2022 – 28 April 2023

Defect

The front caliper mounting bolts may not meet manufacturing specifications and could loosen. This could result in a reduction or loss in braking performance.

Hazard

A reduction or loss in braking performance could increase the risk of an accident causing injury or death to the rider, passenger and other road users.

What to do

Owners of affected vehicles can contact their authorised Yamaha Dealer to schedule an appointment to have the bolts inspected and if required, replaced free of charge.

Contact details

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.com.au/> or CALL 1300 277 137.

If you no longer own this Motorcycle, please advise Yamaha Motor Australia on 1300 277 137 or email cr@yamaha-motor.com.au

Australian Importer/Distributor

Yamaha Motor Australia

489-493 Victoria Street, Wetherill Park

NSW, Australia

See www.productsafety.gov.au for
Australian product recall information